
Chapter 296-803 WAC
Safety Standards for Lockout/Tagout
(Form Number F414-124-000)

LAST UPDATED: 10/06/2017

This book contains rules for Safety Standards for lockout/tagout, as adopted under the Washington Industrial Safety and Health Act of 1973 (Chapter 49.17 RCW).

The rules in this book are effective October 2017. A brief promulgation history, set within brackets at the end of this chapter, gives statutory authority, administrative order of promulgation, and date of adoption of filing.

TO RECEIVE E-MAIL UPDATES:

- Sign up at https://public.govdelivery.com/accounts/WADLI/subscriber/new?topic_id=WADLI_19

TO PRINT YOUR OWN PAPER COPY OR TO VIEW THE RULE ONLINE:

- Go to <https://www.lni.wa.gov/safety-health/safety-rules/rules-by-chapter/?chapter=803/>

DOSH CONTACT INFORMATION:

- **Physical address:**
7273 Linderson Way
Tumwater, WA 98501-5414
(Located off I-5 Exit 101 south of Tumwater.)
- **Mailing address:**
DOSH Standards and Information
PO Box 44810
Olympia, WA 98504-4810
- Telephone: 1-800-423-7233
- For all L&I Contact information, visit <https://www.lni.wa.gov/agency/contact/>

Also available on the L&I Safety & Health website:

- DOSH Core Rules
- Other General Workplace Safety & Health Rules
- Industry and Task-Specific Rules
- Proposed Rules and Hearings
- Newly Adopted Rules and New Rule Information
- DOSH Directives (DD's)
- See <http://www.lni.wa.gov/Safety-Health/>

Chapter 296-803 WAC LOCKOUT/TAGOUT (CONTROL OF HAZARDOUS ENERGY)

WAC	Page
WAC 296-803-099 Definitions.....	1
WAC 296-803-100 Scope.....	3
WAC 296-803-200 Summary.....	5
WAC 296-803-20005 Establish a written energy control program.....	5
WAC 296-803-300 Summary.....	7
WAC 296-803-30005 Make sure new or modified machines and equipment can accept lockout devices.....	7
WAC 296-803-400 Summary.....	8
WAC 296-803-40005 Provide appropriate means to control energy.....	8
WAC 296-803-40010 Make sure lockout and tagout devices meet these requirements.	8
WAC 296-803-40015 Make sure lockout devices meet these additional requirements..	9
WAC 296-803-40020 Make sure tagout devices meet these additional requirements..	9
WAC 296-803-500 Summary.....	10
WAC 296-803-50005 Use energy control procedures.....	11
WAC 296-803-50010 Meet these requirements when applying lockout or tagout devices.....	11
WAC 296-803-50015 Meet these additional requirements when applying lockout devices.....	12
WAC 296-803-50020 Meet these additional requirements when applying tagout devices.....	12

WAC	Page
WAC 296-803-50025 Protect employees from the hazards of stored and residual energy.	12
WAC 296-803-50030 Verify that the machine or equipment is safe before starting work.	13
WAC 296-803-50035 Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment.	13
WAC 296-803-50040 Meet these requirements if it is necessary to temporarily energize a machine, equipment, or component for testing or positioning.	13
WAC 296-803-50045 Protect employees during shift or personnel changes.	14
WAC 296-803-50050 Protect employees working in a group.	14
WAC 296-803-50055 Meet these additional requirements if more than one group is used.	14
WAC 296-803-50060 Coordinate with outside employers servicing or maintaining your machines or equipment.	15
 WAC 296-803-600 Summary.	 16
WAC 296-803-60005 Provide and document employee training on the energy control program.	16
WAC 296-803-60010 Provide additional training if you use tagout devices.	16
WAC 296-803-60015 Retrain employees when necessary.	17
 WAC 296-803-700 Summary.	 18
WAC 296-803-70005 Perform and document periodic reviews to verify employees know and follow the energy control procedures.	18
WAC 296-803-70010 Do periodic reviews of procedures using lockout devices.	18
WAC 296-803-70015 Do periodic reviews of procedures using tagout devices.	19

WAC 296-803-099 Definitions.

Affected employee. An employee who is required to operate, use, or be in the area where a machine or equipment could be locked or tagged out for service or maintenance.

Authorized employee. An employee who locks or tags out a machine or equipment to do service or maintenance.

Can be locked out. An energy-isolating device that can be locked in the "off" or "safe" position.

Employer. Based on chapter 49.17 RCW, an employer is any person, firm, corporation, partnership, business trust, legal representative, or other business entity which engages in any business, industry, profession, or activity in this state and employs one or more employees or who contracts with one or more persons, the essence of which is the personal labor of such person or persons and includes the state, counties, cities, and all municipal corporations, public corporations, political subdivisions of the state, and charitable organizations: Provided, That any persons, partnership, or business entity not having employees, and who is covered by the Industrial Insurance Act must be considered both an employer and an employee.

Energized. Connected to an energy source or containing residual or stored energy.

Energy-isolating device. A mechanical device that physically prevents transmitting or releasing energy. This includes, but is not limited to:

- (a) Manually operated electrical circuit breakers.
- (b) Disconnect switches.
- (c) Manually operated switches that disconnect the conductors of a circuit from all ungrounded supply conductors if no pole of the switch can be operated independently.
- (d) Line valves.
- (e) Blocks.
- (f) Similar devices used to block or isolate energy.

Push buttons, selector switches and other control circuit type devices are not energy isolating devices.

Energy source. Any source of electrical, mechanical, hydraulic, pneumatic, chemical, thermal or other energy, including gravity.

Hot tap. A procedure which involves welding on pressurized pipelines, vessels, or tanks to install connections or accessories. It is commonly used to replace or add sections of pipeline used in air, gas, water, steam, and petrochemical distribution systems without interrupting service.

Lockout. Placing a lockout device on an energy-isolating device using an established procedure to make sure the machine or equipment cannot be operated until the lockout device is removed.

Lockout device. A device that uses a positive means, such as a key or combination lock, to hold an energy-isolating device in the "safe" or "off" position. This includes blank flanges and bolted slip blinds.

Normal production operations. Using a machine or equipment for its intended production function.

Primary authorized employee. An authorized employee who has overall responsibility for meeting the requirements of the lockout/tagout procedures.

Service and maintenance. Activities such as constructing, installing, setting-up, adjusting, inspecting, modifying, maintaining, and servicing machines or equipment. It also includes lubricating, cleaning, unjamming, and making tool changes.

Setting-up. Work done to prepare a machine or equipment for normal production operations.

Tagout. Placing a tagout device on an energy-isolating device using an established procedure to indicate that the energy-isolating device and the machine or equipment being controlled may not be operated until the tagout device is removed.

Tagout device. A prominent warning device, such as a tag and a means of attachment. It can be securely fastened to an energy-isolating device to indicate that the energy-isolating device and the machine or equipment being controlled may not be operated until the tagout device is removed.

You. See definition of employer.

WAC 296-803-100 Scope.

This chapter applies to the service and maintenance of machines and equipment, including piping systems, if employees could be injured by the:

- (1) Unexpected energization or startup of the machine or equipment; or
- (2) Release of stored energy.

Energy sources include mechanical, hydraulic, pneumatic, chemical, thermal, or other energy, including gravity.

Note:

1. Machines and equipment include those that produce high intensity electromagnetic fields.
2. When other Title 296 WAC standards require the use of lockout or tagout, they have to be used and supplemented by the procedural and training requirements of this chapter.

EXEMPTION:

This chapter does not apply to:

1. Construction activities covered by chapter [296-155](#) WAC, Safety standards for construction work.
2. Agriculture activities covered by chapter [296-307](#) WAC, Safety standards for agriculture.
3. Maritime activities covered by chapter [296-56](#) WAC, Safety standards-- Longshore, stevedore and related waterfront operations and chapter [296-304](#) WAC, Safety standards for ship repairing, shipbuilding and shipbreaking.
4. Oil and gas well drilling and servicing.
5. Installations for generating, transmitting, and distributing electrical power (including related communication and metering equipment) that are controlled exclusively by electric utilities.
6. Hot tap operations on pressurized pipelines used to transmit and distribute substances such as gas, steam, water, or petroleum products if the employer can demonstrate that all of the following apply:
 - a. Continuity of service is essential.
 - b. Shutdown of the system is impractical.
 - c. Proven effective employee protection is provided by following documented procedures and using special equipment.
7. Service and maintenance of fire alarm and extinguishing systems and their components if:
 - a. Other employees depend on these systems for fire safety; and
 - b. Employees working on fire extinguishing systems are protected from the unexpected release of hazardous energy by appropriate alternative measures.

EXEMPTION:

8. Work on electric equipment receiving power only through a cord and plug if:
 - a. Unplugging the equipment eliminates the possibility of unexpected energization, unexpected start up, or the release of stored energy; and
 - b. The plug is kept under the exclusive control of the employee doing the service or maintenance.
9. Exposure to electrical hazards from electrical work on, near, or with conductors or equipment that is covered by chapter [296-24](#) WAC, General safety and health standards, Part L, Electrical.
10. Service and maintenance during normal production operations, if an employee is not required to:
 - a. Remove or bypass a guard or other safety device; or
 - b. Place any body part into the point of operation or any other hazardous area created by machine operation.
11. Minor tool changes, adjustments, and other minor service during normal production if:
 - a. They are routine, repetitive, and integral to the use of the equipment for production; and
 - b. The work is done using measures which provide effective protection from hazards.

WAC 296-803-200 Summary.

Your responsibility: To establish an energy control program.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Establish a written energy control program	WAC 296-803-20005

WAC 296-803-20005 Establish a written energy control program.

- (1) You must establish a written energy control program to protect employees that service or maintain a machine or equipment from injury caused by the:
 - (a) Unexpected energization or startup of the machine or equipment; or
 - (b) Release of stored energy.
- (2) You must make sure the program contains **all** of the following:
 - (a) Energy control procedures as described in WAC 296-803-500.
 - (b) Employee training as described in WAC 296-803-600.
 - (c) Periodic reviews as described in WAC 296-803-700.
- (3) You must develop and document in writing energy control procedures to protect employees doing service or maintenance of a machine or equipment from potentially hazardous energy.

EXEMPTION:

You do not have to have written energy control procedures for a particular machine or equipment if all of the following apply:

1. The machine or equipment has a single energy source that is easily identified and can be isolated.
2. The machine or equipment is completely deenergized and deactivated by isolating and locking out the energy source.
3. There is no stored or residual energy that could be a hazard to employees, and the machine or equipment cannot reaccumulate such energy after it has been shut down.
4. The energy source can be locked out with a single lockout device.
5. The machine or equipment is isolated from the energy source and locked out during service or maintenance.
6. The authorized employee doing the service or maintenance has exclusive control of the lockout device.
7. The service or maintenance does not create a hazard for other employees.
8. The machine or equipment has never been unexpectedly energized or activated during service or maintenance.

- (4) You must make sure energy control procedures clearly and specifically outline:
 - (a) The scope, purpose, authorization, rules, and techniques to control hazardous energy; and

- (b) How you will make sure employees follow the procedures.
- (5) You must make sure energy control procedures specifically identify at least the following:
 - (a) When the procedure must be used.
 - (b) What the specific procedural steps are for:
 - (i) Shutting down, isolating, blocking, and securing the machine or equipment.
 - (ii) Placing, moving, and transferring lockout or tagout devices and who is responsible for them.
 - (c) How to test the machine or equipment to verify the effectiveness of lockout devices, tagout devices, and other energy control measures.

Note: Similar machines and equipment may be covered by a single written procedure if all of the following apply:

1. They use the same type and magnitude of energy.
2. They have the same or similar types of controls.
3. The specific machines and equipment covered by the procedure are identified by at least type and location.

WAC 296-803-300 Summary.

Your responsibility: To make sure new or modified machines and equipment can accept lockout devices.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Make sure new or modified machines and equipment can accept lockout devices	WAC 296-803-30005

WAC 296-803-30005 Make sure new or modified machines and equipment can accept lockout devices.

You must make sure energy-isolating devices designed to accept a lockout device are provided on machines and equipment that:

- (1) Are newly installed; or
- (2) Have undergone major replacement , repair, renovation, or modification after July 2, 1990.

WAC 296-803-400 Summary.

Your responsibility: To provide appropriate lockout and tagout devices and means to control energy.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Provide appropriate means to control energy	WAC 296-803-40005
Make sure lockout and tagout devices meet these requirements	WAC 296-803-40010
Make sure lockout devices meet these additional requirements	WAC 296-803-40015
Make sure tagout devices meet these additional requirements	WAC 296-803-40020

WAC 296-803-40005 Provide appropriate means to control energy.

You must provide the means necessary to isolate, secure, or block machines and equipment from energy sources.

Note: Examples of means to control energy include:

1. Locks.
2. Tags.
3. Chains.
4. Wedges.
5. Key blocks.
6. Adapter pins.
7. Self-locking fasteners.
8. Blank flanges.
9. Cribbing.

WAC 296-803-40010 Make sure lockout and tagout devices meet these requirements.

You must make sure lockout and tagout devices meet all of the following:

- (1) Create **no** additional hazards.
- (2) Have a distinctive design or appearance.
- (3) Are the only devices used for controlling energy.
- (4) Are **not** used for any other purpose.
- (5) Are durable enough to withstand the environment they are used in for the maximum time they are expected to be used.
- (6) Are standardized within the facility by color, shape, or size.

- (7) Identify the person applying the device.

WAC 296-803-40015 Make sure lockout devices meet these additional requirements.

You must make sure lockout devices are strong enough so that removing them by other than the normal unlocking method requires:

- (1) Excessive force; or
- (2) Unusual techniques such as the use of bolt cutters or other metal-cutting tools.

WAC 296-803-40020 Make sure tagout devices meet these additional requirements.

- (1) You must make sure all tags:
 - (a) Use the same print and format within a facility.
 - (b) Are constructed and printed so they will not deteriorate and the message on the tag remains legible when:
 - (i) Exposed to weather.
 - (ii) Used in wet or damp locations.
 - (iii) Used in corrosive environments such as areas where acid or alkali chemicals are handled or stored.
 - (c) Have a warning about **not** energizing the machine or equipment.

Note: The warning on the tag should include wording such as:

1. Do not start.
2. Do not open.
3. Do not close.
4. Do not energize.
5. Do not operate.

- (2) You must make sure tagout devices are strong enough to prevent unintentional or accidental removal.
- (3) You must make sure the means used to attach the tag to the energy-isolating device meets all of the following:
 - (a) Is not reusable.
 - (b) Is self-locking.
 - (c) Can be attached by hand.
 - (d) Cannot be released with a force of less than 50 pounds.
 - (e) Is similar in design and basic characteristics to a one-piece, all-environment-tolerant, nylon cable tie.

WAC 296-803-500 Summary.

Your responsibility: To make sure energy control procedures are used and include these requirements.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Energy Control Procedures	
Use energy control procedures	WAC 296-803-50005
Applying Lockout or Tagout Devices	
Meet these requirements when applying lockout or tagout devices	WAC 296-803-50010
Meet these additional requirements when applying lockout devices	WAC 296-803-50015
Meet these additional requirements when applying tagout devices	WAC 296-803-50020
Stored Energy	
Protect employees from the hazards of stored and residual energy	WAC 296-803-50025
Verify that the machine or equipment is safe before starting work	WAC 296-803-50030
Removing Energy Control Devices	
Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment	WAC 296-803-50035
Temporary Energization	
Meet these requirements if it is necessary to temporarily energize a machine, equipment, or component for testing or positioning	WAC 296-803-50040
Shift or Personnel Changes	
Protect employees during shift or personnel changes	WAC 296-803-50045
Group Lockout/Tagout	
Protect employees working in a group	WAC 296-803-50050
Meet these additional requirements if more than one group is used	WAC 296-803-50055
Outside Employers	
Coordinate with outside employers servicing or maintaining your machines or equipment	WAC 296-803-50060

WAC 296-803-50005 Use energy control procedures.

- (1) You must use energy control procedures to protect employees servicing or maintaining machines and equipment from potentially hazardous energy.
- (2) You must use a lockout system if an energy-isolating device can be locked out.

EXEMPTION:

A tagout system may be used instead of a lockout system if it meets **all** of the following:

1. The tagout device is attached where you would have put the lockout device.
2. The tagout system provides the same level of employee protection as a lockout system.
3. You can demonstrate that the tagout system:
 - a. Meets all tagout requirements of this chapter.
 - b. Includes additional safety measures to provide the same level of safety as a lockout system.

Note: Additional safety measures used with the tagout system to provide protection equal to a lockout system could include actions such as:

1. Removing part of the isolating circuit.
2. Blocking a controlling switch.
3. Opening an extra disconnecting device.
4. Removing a valve handle.

- (3) You must use a tagout system if an energy-isolating device cannot be locked out.

WAC 296-803-50010 Meet these requirements when applying lockout or tagout devices.

- (1) You must make sure, before a machine or equipment is turned off, that the authorized employee knows **all** of the following:
 - (a) Type and magnitude of the energy.
 - (b) Hazards of the energy to be controlled.
 - (c) Method or means to control the energy.
- (2) You must turn off or shut down the machine or equipment using established procedures. An orderly shutdown is necessary to avoid any additional or increased hazard to employees as a result of the equipment stoppage.
- (3) You must completely isolate the machine or equipment from its energy sources using the appropriate energy-isolating devices after the machine or equipment has been turned off.
- (4) You must make sure you or the authorized employee notify affected employees that the machine or equipment is being locked or tagged out before the devices are applied.

- (5) You must make sure a lockout or tagout device is applied:
 - (a) For each energy-isolating device.
 - (b) Only by the authorized employee doing the service or maintenance.

WAC 296-803-50015 Meet these additional requirements when applying lockout devices.

You must make sure lockout devices hold the energy-isolating device in a “safe” or “off” position.

WAC 296-803-50020 Meet these additional requirements when applying tagout devices.

- (1) You must make sure a tagout device is put on an energy-isolating device so it clearly shows that moving the energy-isolating device from the “safe” or “off” position is prohibited.
- (2) You must make sure a tagout device, when used with an energy-isolating device that can be locked out, is fastened to the device at the same point a lock would have been attached.
- (3) You must make sure a tagout device that cannot be attached directly to an energy-isolating device is located:
 - (a) As close as safely possible to the energy-isolating device; and
 - (b) In a position that is immediately obvious to anyone attempting to operate the energy-isolating device.

WAC 296-803-50025 Protect employees from the hazards of stored and residual energy.

- (1) You must make sure all potentially hazardous stored and residual energy is relieved, disconnected, restrained, or otherwise rendered safe after the lockout or tagout devices have been put on the energy-isolating devices.
- (2) You must continue to verify the isolation of machines and equipment that could reaccumulate stored energy to a hazardous level until:
 - (a) Service or maintenance is completed; or
 - (b) The possibility of reaccumulating hazardous energy does not exist.

WAC 296-803-50030 Verify that the machine or equipment is safe before starting work.

You must make sure the authorized employee verifies that the machine or equipment that has been locked out or tagged out has been isolated from all energy sources and deenergized before starting work.

WAC 296-803-50035 Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment.

- (1) You must make sure the authorized employee does the following before removing any lockout or tagout device:
 - (a) Inspects the work area to make sure nonessential items have been removed;
 - (b) Verifies the machine or equipment is in operating condition and ready to energize; and
 - (c) Check that employees in the area are in positions that make it safe to energize the machine or equipment.
- (2) You must make sure only the authorized employee who applied a lockout or tagout device removes it.

EXEMPTION:

The employer may have the lockout or tagout device removed by someone other than the authorized employee who applied it if all of the following conditions are met:

1. The energy control program has documented, specific procedures and training for this situation.
2. You can show that the specific procedures used are as safe as having the device removed by the authorized employee who applied it.
3. The specific procedures include at least the following:
 - a. Verifying the authorized employee who applied the device is not at the facility.
 - b. Making all reasonable efforts to contact and inform the authorized employee that the lockout or tagout device is being removed.
 - c. Making sure the authorized employee is informed, before resuming work at the facility, that the lockout or tagout device has been removed.

- (3) You must notify affected employees before energizing or starting the machine or equipment that the lockout or tagout devices have been removed.

WAC 296-803-50040 Meet these requirements if it is necessary to temporarily energize a machine, equipment, or component for testing or positioning.

You must follow your normal energy control procedures to:

- (1) Remove the lockout or tagout devices.

- (2) Energize the machine, equipment, or component.
- (3) Reapply the lockout or tagout devices when testing or positioning is completed.

WAC 296-803-50045 Protect employees during shift or personnel changes.

You must use specific procedures for shift or personnel changes to:

- (1) Make sure there is continuous lockout or tagout protection during the change; and
- (2) Provide for the orderly transfer of lockout or tagout device protection between employees.

WAC 296-803-50050 Protect employees working in a group.

- (1) You must make sure your energy control procedures provide each member of a crew, craft, department, or other group with the same level of protection as that provided by an individual lockout or tagout device.
- (2) You must make sure each authorized employee:
 - (a) Puts a personal lockout or tagout device on the group lockout device, lockbox, or comparable mechanism before beginning work; and
 - (b) Does **not** remove it until they have finished work on the machine or equipment.
- (3) You must assign a primary authorized employee who:
 - (a) Has overall responsibility for the service or maintenance;
 - (b) Attaches their lockout or tagout device to the energy-isolating device when the equipment is deenergized and before any work begins; and
 - (c) Is the last person to remove their lockout or tagout device when the job is completed.

WAC 296-803-50055 Meet these additional requirements if more than one group is used.

You must do **all** of the following if more than one group works on a machine or equipment that has to be locked or tagged out:

- (1) Assign an authorized employee as the group coordinator with overall responsibility to:
 - (a) Coordinate the different work groups; and
 - (b) Maintain continuous lockout or tagout protection.
- (2) Assign a primary authorized employee in each group who has:
 - (a) Responsibility for the group of employees who are protected by a group lockout or tagout device; and
 - (b) A way to determine which employees of the group are exposed to the machine or equipment that is locked or tagged out.

WAC 296-803-50060 Coordinate with outside employers servicing or maintaining your machines or equipment.

You must do the following before allowing another employer's personnel to service or maintain machines or equipment if your energy control procedures require they be locked or tagged out:

- (1) Inform the outside employer of your lockout or tagout procedures.
- (2) Make sure the outside employer informs you of their lockout or tagout procedures.
- (3) Make sure you and the outside employer confirm that all employees understand and will follow the restrictions of the other employer's energy control program.

WAC 296-803-600 Summary.

Your responsibility: To train employees on your energy control program.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Provide and document employee training on the energy control program	WAC 296-803-60005
Provide additional training if you use tagout devices	WAC 296-803-60010
Retrain employees when necessary	WAC 296-803-60015

WAC 296-803-60005 Provide and document employee training on the energy control program.

- (1) You must train employees to make sure that they:
 - (a) Understand the purpose and function of the energy control program; and
 - (b) Have the knowledge and skills necessary to carry out their program responsibilities.
- (2) You must train each authorized employee in:
 - (a) The type and magnitude of energy available in the workplace.
 - (b) Recognizing hazardous energy sources that apply.
 - (c) Methods and means to isolate and control energy.
- (3) You must instruct each affected employee in the purpose and use of the energy control procedures.
- (4) You must instruct all employees who work or may work where energy control procedures might be used about the:
 - (a) Procedures being used; and
 - (b) Prohibition against attempting to restart or reenergize a machine or equipment that is locked out or tagged out.
- (5) You must document that employee training has been done and kept up to date.
Include the employee's name and the training date.

WAC 296-803-60010 Provide additional training if you use tagout devices.

You must make sure employees are trained in the following:

- (1) Tags are warning devices and do not provide the same level of physical restraint as a lock.
- (2) When attached to energy-isolating devices, tags are not to be:

- (a) Removed without the approval of the authorized person responsible for it; or
 - (b) Bypassed, ignored, or otherwise defeated.
- (3) Tags need to be legible and understandable to be effective.
- (4) Tags may evoke a false sense of security.
- (5) The meaning of tags needs to be understood as part of the overall energy control program.
- (6) Tags and their means of attachment must be:
- (a) Securely attached to energy-isolating devices so they cannot be inadvertently or accidentally detached; and
 - (b) Made of materials that will withstand the environmental conditions they are be exposed to.

WAC 296-803-60015 Retrain employees when necessary.

- (1) You must retrain authorized and affected employees to introduce new or revised control methods and procedures when there is a change in **any** of the following:
- (a) Job assignments.
 - (b) Machines, equipment, or processes that present a new hazard.
 - (c) Energy control procedures.
- (2) You must retrain employees to reestablish proficiency when:
- (a) A periodic review shows the employee deviates from, or has inadequate knowledge of, the energy control procedures; or
 - (b) The employer has reason to believe retraining is necessary.

WAC 296-803-700 Summary.

Your responsibility: To do periodic reviews to make sure employees know and use your energy control procedures.

<i>You must meet the requirements...</i>	<i>in this section:</i>
Perform and document periodic reviews to verify employees know and follow the energy control procedures	WAC 296-803-70005
Do periodic reviews of procedures using lockout devices	WAC 296-803-70010
Do periodic reviews of procedures using tagout devices	WAC 296-803-70015

WAC 296-803-70005 Perform and document periodic reviews to verify employees know and follow the energy control procedures.

- (1) You must do a periodic review at least annually to:
 - (a) Make sure employees know and can apply the energy control procedures.
 - (b) Correct any deviations or inadequacies identified.

EXEMPTION:

Energy control procedures used less frequently than once a year only need to be reviewed before being used.

- (2) You must have the periodic review done by an authorized employee other than the ones using the energy control procedure being reviewed.
- (3) You must document that periodic reviews have been done.

Include all of the following:

 - (a) Machine or equipment the energy control procedure was used for.
 - (b) Date of the review.
 - (c) Employees included in the review.
 - (d) Person doing the review.

WAC 296-803-70010 Do periodic reviews of procedures using lockout devices.

You must make sure, if a periodic review involves lockout devices, the reviewing employee reviews responsibilities with each authorized employee who uses the procedure.

Note: Periodic reviews of authorized employees using energy control procedures involving only lockout devices can be done in a group meeting if desired.

WAC 296-803-70015 Do periodic reviews of procedures using tagout devices.

You must make sure, if a periodic review involves tagout devices, the reviewing employee reviews with each authorized and affected employee the:

- (1) Employee's responsibilities under the procedure; and
- (2) Limitations of tagout devices.

Note: Periodic reviews of authorized and affected employees using energy control procedures involving tagout devices have to be done with each employee individually.

Reference: See WAC 296-803-60010, Provide additional training if you use tagout devices, in this chapter for the limitations of tagout devices.

WAC 296-802-099 Definitions.

Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-099, filed 09/05/2017, effective 10/06/2017.]

WAC 296-803-100 Scope.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-100, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-100, filed 07/20/04, effective 11/01/04.]

WAC 296-803-200 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-200, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-200, filed 07/20/04, effective 11/01/04.]

WAC 296-803-20005 Establish a written energy control program.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-20005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-20005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-300 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-300, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-300, filed 07/20/04, effective 11/01/04.]

WAC 296-803-30005 Make sure new or modified machines and equipment can accept lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-30005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-30005, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-30005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-400 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-400, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-400, filed 07/20/04, effective 11/01/04.]

WAC 296-803-40005 Provide appropriate means to control energy.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-40005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-40005, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-40010 Make sure lockout and tagout devices meet these requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-40010, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40010, filed 07/20/04, effective 11/01/04.]

WAC 296-803-40015..Make sure lockout devices meet these additional requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-40015, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40015, filed 07/20/04, effective 11/01/04.]

WAC 296-803-40020 Make sure tagout devices meet these additional requirements.

[Statutory Authority: Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-40020, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40020, filed 07/20/04, effective 11/01/04.]

WAC 296-803-500 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-500, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-500, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50005 Use energy control procedures.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50010 Meet these requirements when applying lockout or tagout requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50010, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-50010, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50010, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50015 Meet these additional requirements when applying lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50015, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50015, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50020 Meet these additional requirements when applying tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50020, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50020, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50025 Protect employees from the hazards of stored and residual energy.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50025, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50025, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50030 Verify that the machine or equipment is safe before starting work.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50030, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50030, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50035 Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50035, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50035, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50040 Meet these requirements if it is necessary to temporarily energize a machine, equipment, or component for testing or positioning.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50040, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50040, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50045 Protect employees during shift or personnel changes.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50045, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50045, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50050 Protect employees working in a group.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50050, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50050, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50055 Meet these additional requirements if more than one group is used.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50055, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50055, filed 07/20/04, effective 11/01/04.]

WAC 296-803-50060 Coordinate with outside employers servicing or maintaining your machines or equipment.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-50060, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50060, filed 07/20/04, effective 11/01/04.]

WAC 296-803-600 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-600, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-600, filed 07/20/04, effective 11/01/04.]

WAC 296-803-60005 Provide and document employee training on the energy control program.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-60005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-60010 Provide additional training if you use tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-60010, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60010, filed 07/20/04, effective 11/01/04.]

WAC 296-803-60015 Retrain employees when necessary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-60015, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-60015, filed 08/04/09, effective 11/10/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60015, filed 07/20/04, effective 11/01/04.]

WAC 296-803-700 Summary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-700, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-700, filed 07/20/04, effective 11/01/04.]

WAC 296-803-70005 Perform and document periodic reviews to verify employees know and follow the energy control procedures.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-70005, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70005, filed 07/20/04, effective 11/01/04.]

WAC 296-803-70010 Do periodic reviews of procedures using lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-70010, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70010, filed 07/20/04, effective 11/01/04.]

WAC 296-803-70015 Do periodic reviews of procedures using tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 17-18-075 (Order 16-17), § 296-803-70015, filed 09/05/2017, effective 10/06/2017. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70015, filed 07/20/04, effective 11/01/04.]

Sample Lockout Procedure

Use with Lockout/Tagout (Control of Hazardous Energy), Chapter 296-803 WAC

The following sample lockout procedure contains the minimum information necessary to help you develop an energy control procedure that meets the requirements of Lockout/Tagout (Control of Hazardous Energy), Chapter 296-803 WAC.

Complex systems may require you to develop, document, and use more comprehensive procedures.

You can use this fill-in-the-blank template, or develop your own form.

Note:

If you develop your own form, remember to include the necessary information from this template.

Fill-in-the blank Template

SCOPE:

This lockout procedure is for:

*Company Name if you only use a single procedure (one machine or type of machine); or
Specific machine or equipment that this procedure applies to, if you use multiple procedures.
For additional information, see WAC 296-803-20005, in this chapter).*

PURPOSE:

This procedure establishes the minimum requirements necessary to protect employees from injury caused by the unexpected energization, start up, or release of stored energy during service or maintenance.

Use this procedure to make sure the machine or equipment is stopped, isolated from all potentially hazardous energy sources, and locked out before any employee begins work.

AUTHORIZATION:

The following persons are authorized to lock out the machine or equipment using this procedure:
(List the names of authorized employees you want to use this procedure)

COMPLIANCE WITH THIS PROGRAM:

All employees are required to comply with the restrictions and limitations imposed upon them during the use of lockout.

Authorized employees will perform lockout as described in this procedure.

No employee will attempt to start, energize or use any machine or equipment that is locked out.

Failure to comply with this procedure will result in the following action:

(List the actions that will be taken if employees violate the procedure)

INTENDED USE:

This procedure will be used for the following service or maintenance actions:

(List the service and maintenance activities that require using the procedure)

SPECIFIC PROCEDURAL STEPS:

Step 1: The authorized employee will identify the type and magnitude of the energy that the machine or equipment uses, understand the hazards of the energy, and the methods to control the energy before using this procedure.

(List the type and magnitude of the energy, its hazards, and the methods to control the energy. For additional information, see WAC 296-803-50010, in this chapter)

Step 2: Notify all affected employees that the machine or equipment is to be shut down and locked out for service or maintenance.

(List the names or job titles of affected employees and how to notify them. For additional information, see WAC 296-803-50010, in this chapter)

Step 3: Shut down the machine or equipment by the normal stopping procedure (such as depressing a stop button, opening switches, or closing valves).

(List types and locations of machine or equipment operating controls. For additional information, see WAC 296-803-50010, in this chapter)

Step 4: Completely isolate the machine or equipment from its energy sources by using the appropriate energy-isolating devices.

(List types and locations of energy isolating devices. For additional information, see WAC 296-803-50010, in this chapter)

SPECIFIC PROCEDURAL STEPS: (continued)

Step 5: Lock out the energy isolating devices with assigned individual locks.

(List any additional procedural requirements, such as putting on a tag with amplifying information, necessary for the authorized employee to know. For additional information, see WAC 296-803-50010, in this chapter)

Step 6: Dissipate or restrain stored and residual energy, such as that in capacitors, springs, elevated machine members, rotating flywheels, hydraulic systems, and air, gas, steam, or water pressure, using methods such as grounding, repositioning, blocking, or bleeding down.

(List the types of stored and residual energy and the methods to dissipate or restrain them. For additional information, see WAC 296-803-50025, in this chapter)

(List any actions necessary to prevent stored energy from reaccumulating to a hazardous level. For additional information, see WAC 296-803-50025, in this chapter)

Step 7: Make sure the equipment is disconnected from the energy sources and stored and residual energy has been made safe. Check that no personnel are exposed, then verify the isolation of the equipment by doing the following:

(List the method of verifying machine or equipment isolation, such as operating the push button or other normal operating controls or by testing to make certain the equipment will not operate. For additional information, see WAC 296-803-50030 in this chapter)

CAUTION: Return the operating controls to the safe, neutral, or off position, after verifying the equipment is isolated from its energy sources.

THE MACHINE OR EQUIPMENT IS NOW LOCKED OUT

Restore the machine or equipment to service after the service or maintenance is completed and the machine or equipment is ready to return to its normal operating condition by doing the following steps:

(For additional information, see WAC 296-803-50035, in this chapter)

Step 1: Check the machine or equipment and the immediate area around it to make sure all nonessential items have been removed and that the machine or equipment is in operating condition and ready to energize.

Step 2: Make sure all employees are safely positioned for starting or energizing the machine or equipment.

Step 3: Verify that the controls are in neutral.

Step 4: Remove the lockout devices and reenergize the machine or equipment.

Note: Some forms of blocking may require re-energization of the machine before they can be safely removed.

Step 5: Notify affected employees that the servicing or maintenance is completed and the machine or equipment is ready to use.