

## Roofing Contractor Falls 25 Feet from Church Roof

**Industry: Roofing Contractors**

**Task: Nailing down roofing materials**

**Occupation: Roofing contractor**

**Type of Incident: Fall from roof**





# ***FATALITY NARRATIVE***

In September of 2015, a 34-year-old roofing contractor died after falling 25 feet from a church roof.

The victim was a co-owner of a father and son roofing company. He and his father were subcontracted to complete a roof on a newly constructed church. Both were experienced roofers. They had been working on the site for about a week.

On the day of the incident, the weather was sunny and warm. They were the only workers at the site, and both were working on the roof. It was a low pitch roof with a 1 in 12 slope. The victim was working on the edge of the roof nailing down roofing materials. Neither of the roofers was using fall protection, nor was there any in place on the roof or on site. The father looked up from his work and did not see his son on the roof. He went to the side of the roof where his son had been and looked down. His son was lying on the sidewalk below, bleeding. He had fallen 25 feet from the roof edge.

The father attempted CPR and then called 911. First responders arrived and, after attempting further CPR, declared the victim deceased.



Incident scene showing the church roof edge from which the victim fell 25 feet to the sidewalk.



# *FATALITY NARRATIVE*

## **Requirements**

### **Plan.**

Develop and implement a written fall protection work plan that includes each area of the work place where employees are assigned and where hazards of ten feet or more exist.

See [WAC 296-155-24611\(2\)\(a\)](#)



# *FATALITY NARRATIVE*

## **Requirements**

### **Provide.**

Ensure that the appropriate fall protection system is provided, installed, and implemented when employees are exposed to fall hazards of 10 feet or more to the ground or lower level while engaged in roofing work on a low pitched roof. A low pitched roof has a slope equal to or less than 4 in 12.

See [WAC 296-155-24611\(1\)\(a\)](#)



# *FATALITY NARRATIVE*

## **Requirements**

### **Train.**

Prior to permitting employees into areas where fall hazards exist you must ensure employees are trained and instructed in the items described in the fall protection work plan.

See [WAC 296-155-24611\(2\)\(b\)](#)



# *FATALITY NARRATIVE*

## **Recommendation**

Under specific circumstances, business owner/operators may be exempt from workplace regulations, as was the case in this incident. However, they are advised to follow safe work practices.



# ***FATALITY NARRATIVE***

## **Resources**

- Roofing Work. Washington State Department of Labor and Industries.  
[www.lni.wa.gov/Safety/Topics/AtoZ/RoofingWork/](http://www.lni.wa.gov/Safety/Topics/AtoZ/RoofingWork/)
- Protecting Roofing Workers. OSHA  
[www.osha.gov/Publications/OSHA3755.pdf](http://www.osha.gov/Publications/OSHA3755.pdf)





# ***FATALITY NARRATIVE***

*This bulletin was developed to alert employers and employees of a tragic loss of life of a worker in Washington State and is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.*

Developed by Washington State Fatality Assessment and Control Evaluation (FACE) Program and the Division of Occupational Safety and Health (DOSH), Washington State Dept. of Labor & Industries. The FACE Program is supported in part by a grant from the National Institute for Occupational Safety and Health (NIOSH grant# 2U60OH008487-11). For more information, contact the Safety and Health Assessment and Research for Prevention (SHARP) Program, 1-888-667-4277.